

Exhibit B-1 and B-2: Photos illustrating conditions of northern portion of Holly Pond Inlet at low tide. The bridge shown is the Rt. 1 bridge; the building at the right is *Giovanni's*.



Exhibit B-3 and B-4: Photos illustrating conditions of northern portion of Holly Pond Inlet at low tide. The park at left in Exhibit 10c is Gehrlı park.





Exhibit B-5 and B-6: Photos illustrating conditions of southern portion of Holly Pond Inlet at mid-tide. The birds shown in photos can typically stand on the southern shoal at all times except the peak high tide.



Exhibit B-7 and B-8: Photos illustrating the wetland flora present along the shoreline on the eastern side of the inlet. The birds shown in photos are on top of the southern shoal.



Exhibit B-9 and B-10: Exhibit 10i illustrates the wetland flora present along the shoreline on the eastern side of the inlet. Exhibit 10j illustrates the southern shoal during a falling tide.



Exhibit B-11 and B-12: Illustrates the wetland flora present along the shoreline on the eastern side of the inlet. Exhibit 10k also shows the southern shoal during a falling tide.