

Community Living Arrangement Inspection Report Summary

Second Hill

193 Second Hill Road New Milford, CT 06776

R-1177

Sunrise Northeast, Inc.

Inspection Date: Tuesday, April 03, 2012

DDS Region: West

Inspection Type: Revisit

Inspection Report Citations Were Reported In The Following Regulatory Areas:

Regulatory Category

17a-227-05	Plans of Correction
5b	POC implementation timeliness
17a-227-11	Physical Requirements
11d	Hazard prevention
17a-227-12	Emergency Planning
12b	Emergency response training/monthly fire drills