

Community Living Arrangement Inspection Report Summary

Brierwood Avenue

96 Brierwood Avenue Watertown, CT 06795

R-1276

OAK HILL

Inspection Date: Tuesday, January 19, 2016

DDS Region: West

Inspection Type: Initial

Inspection Report Citations Were Reported In The Following Regulatory Areas:

Regulatory Category

17a-227-11	Physical Requirements
11c	Home safety inspections